

### TIMING IDLER SPROCKET FAILURE - SUZUKI H27A V6 DOHC 24V


Fig 1  
Idler Sprocket



Fig 2  
Idler Shaft



Fig 3



Due To The High Loads That Are Carried By The Idler Sprocket ( Fig1) It Is Essential That The Idler Shaft ( Fig 2 ) Be Replaced In Conjunction With One Another. This Is Due To Wear & Also The Typical Failure Point Being The Idler Sprocket, Damaging The Idler Shaft Mating Surface.

Fig 1; Idler Sprocket

Fig 2; Idler Shaft, **Must Be Fitted** In Conjunction With Idler Sprocket

Fig 3; Fig 1 & 2 Displayed As 5 & 6 On Timing Layout Diagram