



**PRODUCT  
BULLETIN  
NPB - 17**

## MOUNTING BOLT FAILURE

MITSUBISHI 4D56Di-T DOHC TIMING BELT TENSIONER IN NASON TIMING BELT KITS  
**MBTK35 & MBTK35HT**

Nason timing belt kits MBTK35 & MBTK35HT both contain the OEM Genuine NTN timing belt tensioner assembly which includes a special allen head shoulder bolt held in place by a plastic sleeve.



When removing the plastic sleeve. It is important that the spacer washer remains in its intended place on the assembly and is included when fitting the tensioner to the engine.

It is critical that the M10 bolt be tightened down to a torque of **42 – 54 Nm.** Once fitted check that the tensioner assembly pivots freely at its mounting point.