

NASON

ENGINE PARTS



2015

Hydraulic Tensioners









1300 662 766

PART #	PHOTO	MODEL / FITMENT	GATES # / (CBC)	DAYCO #
NBT102-OE		TOYOTA 1G-FE 2.0L 6CYL DOHC 24V Intergrated Hydraulic Tensioner	(TT052)	KT192
NBT988-OE		MAZDA WL-C & WE DIESEL 2.5/3.0L 4CYL DOHC 16V Intergrated Hydraulic Tensioner		KT172
NBTH002-OE		HYUNDAI G6BA G6BV 2.5/2.7L V6 DOHC 24V ** Can use NBTH1075-OE **	(HYT100)	HAT18
NBTH003-OE		HYUNDAI G6CTX 3.0L V6 DOHC 24V	(HK1001)	HAT17
NBTH004-OE		Toyota 1MZ-FE 3MZ-FE 3.0L V6 DOHC 24V	(TTH90S3)	HAT06
NBTH005-OE		Mitsubishi 6G72 6G75 3.0/3.8L V6 SOHC 24V	(MIT861)	HAT21
NBTH006		HONDA H22A1 H22A4 2.2L 4CYL DOHC 16V		N/A
NBTH007		Mitsubishi 6B31 3.0L V6 SOHC 24V		HAT42

NBTH008		VOLKSWAGEN AWU AGU AWT 1.8L 4CYL DOHC 20V	(AUT069)	HAT502
NBTH009		CHRYSLER NEON 2.0L 4CYL DOHC 16V	(CT587)	HAT35
NBTH970		SUBARU EJ20 EJ25 2.0/2.5L 4CYL S/DOHC 16V	GHT20 (SUH051)	HAT22
NBTH1000-OE		SUBARU EJ16 EJ20 EJ25 EJ22 1.6 To 2.5L 4CYL S/DOHC 16V	GHT09 (SUH006J)	HAT07
NBTH1001-OE		MITSUBISHI 4G64-4 2.4L 4CYL SOHC 16V		HAT32
NBTH1002-OE		TOYOTA 1UZ-FE 2UZFE 4.0/4.7L V8 DOHC 32V	GHT08	HAT11
NBTH1002-OE		34.5 MM Distance between bolt holes		
NBTH1003		HONDA J30/35 3.0/3.5L V6 SOHC 24V		HAT29

NBTH1004		HONDA J30A1 3.0L V6 SOHC 24V		HAT36
NBTH1005		NISSAN VG30DE 3.0L V6 DOHC 24V		N/A
NBTH1010-OE		TOYOTA 1HD-FT 1HD-FTE 4.2L 6CYL SOHC 24V	GHT07 (TTH301)	HAT12
NBTH1015-OE		Toyota 1MZ-FE 3MZ-FE 3.0L V6 DOHC 24V	GHT02	HAT10
NBTH1015-OE		57.60 MM Distance between bolt holes		
NBTH1025-OE		LEXUS 1,2 3UZFE 2JZ 6CYL & V8 DOHC 24/32V	(TTH0093)	HAT28
NBTH1025-OE		51.75 MM Distance between bolt holes		
NBTH1031		MITSUBISHI 4G93 4G93T 1.8L 4CYL DOHC 16V		HAT05

<p>NBTH1035-OE</p> 		<p>TOYOTA 3VZ-FE , 5VZ-FE 3.0/3.4L V6 DOHC 24V</p>	<p>GHT21</p>	<p>HAT27</p>
<p>NBTH1035-OE</p> 		<p>57.20 MM Distance between bolt holes</p>		
<p>NBTH1045-OE</p> 		<p>TOYOTA 1KZ-TE 1/2KD-FTV 4CYL 2.5 / 3.0L S/DOHC 8V & 16V</p>	<p>GHT06 (TTH3018)</p>	<p>HAT13</p>
<p>NBTH1050-OE</p> 		<p>TOYOTA 3S-GE 2.0L 4CYL DOHC 16V Bolt holes are 11mm.</p>		<p>N/A</p>
<p>NBTH1055-OE</p> 		<p>TOYOTA 3S-GTE 2.0L 4CYL DOHC 16V Bolt holes are 8mm.</p>		<p>N/A</p>
<p>NBTH1060</p> 		<p>TOYOTA 3SGTE MR2 2.0L 4CYL DOHC 16V Bolt holes are 8mm with a 6mm screw hole.</p>	<p>(HT480)</p>	<p>N/A</p>
<p>NBTH1065</p> 		<p>ISUZU 6VD1 3.2L V6 SOHC 24V Length 90.85mm</p>	<p>GHT05</p>	<p>HAT14</p>
<p>NBTH1070-OE</p> 		<p>ISUZU 6VD1 6VE1 3.2 / 3.5L V6 DOHC 24V Length 69.5mm</p>	<p>GHT04</p>	<p>HAT16</p>

NBTH1074-OE		MITSUBISHI 4D56Di-T 2.5L 4CYL DOHC 16V Common Rail		HAT41
NBTH1075-OE		HYUNDAI, MITSUBISHI 4G63 G4CP G4CR G4CN 1.6 To 2.0L 4CYL DOHC 16V MUST have central bolt hole for timing cover	(MH533)	HAT03
NBTH1076-OE		MITSUBISHI LANCER EVO 4 TO 7 2.0L 4CYL DOHC 16V	(HT086)	HAT40
NBTH1077-OE		MITSUBISHI 4G15/T 1.5L 4CYL DOHC 16V		N/A
NBTH1080-OE		MITSUBISHI 6G72 6G74 6G75 3.0 To 3.8L V6 S/DOHC 24V	GHT01 (MT622)	HAT01
NBTH1085		MITSUBISHI 4G63 2.0L 4CYL DOHC 16V	GHT19	HAT04
NBTH1090-OE		HYUNDAI/MITSUBISHI G4JP, G4JS, 4G63 4G63-T 2.0L 4CYL DOHC 16V	GHT18	HAT02
NBTH1095-OE		MITSUBISHI 6A12 2.0L V6 DOHC 24V	(MH593)	HAT24

NBTH1101		KIA K5 2.5L V6 DOHC 24V	(MKF827)	HAT20
NBTH1102-OE		HYUNDAI / KIA G6EA 2.7L V6 DOHC 24V		HAT39
NBTH2000		MITSUBISHI 6G74 3.5L V6 DOHC 24V	(MH040)	HAT25
NBTH2006		FORD/MAZDA JE 3.0L V6 SOHC 18V		HAT08
NBTH2007		MAZDA JE-ZE 3.0L V6 DOHC 24V	GHT11	HAT23
NBTH2008-OE		MAZDA 6 MZR-CD 2.2L 4CYL SOHC 16V DIESEL		HAT38
NBTH421		FORD MAZDA K8 KF KL 1.8 / 2.0 / 2.5L V6 DOHC 24V	GHT10 (FM207)	HAT09