


PRODUCT BULLETIN
NPB-01



MAZDA / FORD EGR COOLER ASSEMBLY

NASONS PART NUMBER EGRWE-OE

To Suit The Following
Mazda BT50 2.5L DOHC 16v WL-C 2006-11
Mazda BT50 3.0L DOHC 16v WE-C 2006-on
Ford Ranger PJ 3.0L DOHC 16v WE-C 2006-on
OEM # WE05 20304



Overheating ?

Question,

For Coolant to enter the combustion chamber it has to go through the head gasket ?

Not completely true, the exhaust gas comes through the EGR pipe off your EGR valve and runs through the exhaust gas cooler which has coolant from your radiator passing through it to cool the gas before it returns to the inlet side of the motor.

If the exhaust gas cooler fails then coolant can get into the exhaust gas recirculation pipes and end up back in the engine via your intake..

We recommend....

You inspect your EGR Cooler Assembly if replacing your head and or head gasket to ensure there is no repeat of over heating .

Nason Engine Parts 1300 662 768